

## **HILL HEAD SAILING CLUB**

### **HARBOUR SURVEY 2007**

If you were out and about between Christmas and New Year you might have seen Sue and I doing some surveying around the club. The idea was to provide the basis for instructing the contractor, who will soon be removing the shingle bank from the harbour entrance; and to provide hard information to support the design of new sea defences on the spit.

Sue and I both have some surveying experience but it was a long time ago and we had to re-learn some long-forgotten skills to do it again. The club paid for the hire of an electronic theodolite (which was much superior to the equipment we used to use) and while we had it we surveyed both dinghy parks to provide accurate scale drawings of these areas too. The attached picture is an extract from the survey drawing. I hope you recognise it.

Here are some links to the drawings:

- Spit Side Dinghy Park (1:250 A3)
- Club Side Dinghy Park (1:250 A3)
- Harbour Entrance (1:250 A3)
- Overall Survey Sheet 1 (1:500 A2)
- Overall Survey Sheet 2 (1:500 A2)

Dave and Sue Ellis